



Agenda

- Welcome and Check-In
- OPN Update on Secondary Data Collection
- District Projected Data from RSP
 - Projected data
- Elementary Next Steps
- Review Calendar of Dates
- Closure









District Middle & High Schools | Kennedy | Harding | Ha

Condition Photos











Cedar Rapids Community School District

Condition Photos












Facility Assessment






Site Deficiencies

- 1. Cross slope in excess of 2.0%
- 2. Longitudinal slope in excess of 2.0%
- 3. Cross slope in excess of 2.0%
- 4. Longitudinal slope in excess of 2.0%
- 5. Exit and route not ADA compliant








Cedar Rapids Community School District





Φ

















 Site Improvements
 \$ 80,750

 Building Exterior
 \$20,705,315

 Interior Deficiencies
 \$ 4,796,776

 Mechanical
 \$ 4,876,000

 Electrical
 \$ 3,215,000

 Food Service
 \$ 210,000

 General Conditions
 \$ 2,033,030

SUBTOTAL \$ 35,916,871





McKinley Middle School

143,230 GSF SCHOOL SIZE 700 NSF AVG CLASSROOM





Site Deficiencies

- 1. ADA parking spaces exceed 2% in any direction
- 2. Accessible route exceeds 2% cross slope
- 3. General Note: Only 3 exit doors without steps




OPN ARCHITECTS





ADA/Code Compliance

- 1. Non-compliant fixtures and stalls in restrooms
- 2. Non compliant room entries, hallway and door construction
- 3. Non-compliant stair handrails
- Insufficient exiting, dead end corridors
- 5. Rooms and areas are completely inaccessible or not accessible through typical route
- 6. Room capacity exceeds existing capacity
- 7. Food Service:
 - 1. Refrigerated storage cannot maintain proper temperatures
 - 2. Undersized equipment
 - 3. Equipment beyond life expectancy








Cedar Rapids Community School District

ADA/Code Compliance

- 1. Non-compliant fixtures and stalls in restrooms
- 2. Non compliant room entries, hallway and door construction
- 3. Non-compliant stair handrails
- 4. Insufficient exiting, dead end corridors
- 5. Rooms and areas are completely inaccessible or not accessible through typical route
- 6. Room capacity exceeds existing capacity
- 7. Food Service:
 - 1. Refrigerated storage cannot maintain proper temperatures
 - 2. Undersized equipment
 - 3. Equipment beyond life expectancy






O Level 1



ADA/Code Compliance

- 1. Non-compliant fixtures and stalls in restrooms
- 2. Non compliant room entries, hallway and door construction
- 3. Non-compliant stair handrails
- Insufficient exiting, dead end corridors
- 5. Rooms and areas are completely inaccessible or not accessible through typical route
- 6. Room capacity exceeds existing capacity
- 7. Food Service:
 - 1. Refrigerated storage cannot maintain proper temperatures
 - 2. Undersized equipment
 - 3. Equipment beyond life expectancy








Cedar Rapids Community School District


ADA/Code Compliance


- 1. Non-compliant fixtures and stalls in restrooms
- 2. Non compliant room entries, hallway and door construction
- 3. Non-compliant stair handrails
- 4. Insufficient exiting, dead end corridors
- 5. Rooms and areas are completely inaccessible or not accessible through typical route
- 6. Room capacity exceeds existing capacity
- 7. Food Service:
 - 1. Refrigerated storage cannot maintain proper temperatures
 - 2. Undersized equipment
 - 3. Equipment beyond life expectancy



O Level 3

OPN





 Site Improvements
 \$ 111,350

 Building Exterior
 \$19,470,146

 Interior Deficiencies
 \$ 3,898,329

 Mechanical
 \$ 4,380,000

 Electrical
 \$ 2,855,000

 Food Service
 \$ 255,000

 General Conditions
 \$ 1,858,189

SUBTOTAL \$ 32,828,014



Cedar Rapids Community School District

Roosevelt Middle School

147,687 GSF SCHOOL SIZE 700 NSF AVG CLASSROOM







Site Deficiencies


- 1. Slope in excess of 2.0%, Not van accessible
- ADA parking stalls are not located on an accessible route. 1 of 3 entrance/exit doors that does not have steps and ADA parking is located too far away
- One of 3 entrance/exit doors that does not have steps and slope exceeds 5% without handrails and 8.3% with rails
- 4. One of 3 entrance/exit doors that does not have steps and slope exceeds 5% without handrails
- 5. ADA parking stalls exceed 2% in any direction. ADA parking stalls without a compliant route to any location
- 6. General Note: Only 3 exit doors without steps














ADA/Code Compliance 1. Non-compliant fixtures and stalls in restrooms 2. Non compliant room entries, hallway and door construction Non-compliant stair handrails Insufficient exiting, dead end corridors 5. Rooms and areas are completely inaccessible or not accessible through typical route 6. Room capacity exceeds existing capacity 7. Food Service: 1. Refrigerated storage cannot maintain proper temperatures 2. Undersized equipment 3. Equipment beyond life expectancy O Level 1 OPN Cedar Rapids Community School District



ADA/Code Compliance 1. Non-compliant fixtures and stalls in restrooms Non compliant room entries, hallway and door construction Non-compliant stair handrails Insufficient exiting, dead end corridors 5. Rooms and areas are completely inaccessible or not accessible through typical route 6. Room capacity exceeds existing capacity 7. Food Service: 1. Refrigerated storage cannot maintain proper temperatures 2. Undersized equipment 3. Equipment beyond life expectancy O Level 3 OPN Cedar Rapids Community School District





 Site Improvements
 \$ 38,025

 Building Exterior
 \$19,898,168

 Interior Deficiencies
 \$ 4,898,029

 Mechanical
 \$ 4,340,000

 Electrical
 \$ 2,865,000

 Food Service
 \$ 255,000

 General Conditions
 \$ 1,937,653

SUBTOTAL \$ 34,231,876






OPN ARCHITECTS

Wilson


89,664 GSF SCHOOL SIZE 675 NSF AVG CLASSROOM


Site Deficiencies


- 1. Cross slope in excess of 2%
- 2. No existing compliant route from ADA parking spaces
- 3. Entrance / exit not ADA compliant
- 4. Sidewalk route not ADA compliant
- 5. ADA parking spaces are not compliant slope and change in elevation
- 6. Parallel stalls not ADA compliant





OPN ARCHITECTS

















 Site Improvements
 \$ 248,000

 Building Exterior
 \$19,367,615

 Interior Deficiencies
 \$ 4,491,892

 Mechanical
 \$ 2,780,000

 Electrical
 \$ 2,015,000

 Food Service
 \$ 320,000

 General Conditions
 \$ 1,753,350

SUBTOTAL \$ 30,975,857



Total Assessment Cost

 Franklin
 \$35,916,871

 McKinley
 \$32,828,014

 Roosevelt
 \$34,231,876

 Wilson
 \$30,975,857

 Harding
 \$ 8,674,136

 Taft
 \$ 8,169,152

SUBTOTAL \$150,795,906



Cedar Rapids Community School District

District Data-RSP Data



