



Agenda


- Welcome and Check-In
- Elementary Input and Feedback from December 21 meeting
- District Demographic Data-BIG Picture
- District Projected Data–Rob from RSP
 - Current data
 - Projected data
- Update on Secondary Data Collection—Susan from OPN
- Next Steps















District Demographic Data Review





































TAFT MIDDLE SCHOOL


- 111,440 GSF
- 750 NSF AVG CLASSROOM







Site Deficiencies

- Parking longitudinal slope in excess of 2.0%
- 2. ADA parking space not accompanied by an access aisle
- 3. Ramp slope is not compliant
- A-H: Non-accessible exit / entrance








Physical Assessment

ADA Code Compliance / Taft Middle School


- Non-compliant fixtures and stalls in restrooms
- 2. Non-ADA casework and sinks
- Non-compliant stairs / guard rails, no handrails
- 4. No ADA accessible seating
- 5. Food Service:
 - 1. Serving equipment cannot maintain proper temperatures
 - 2. Undersized equipment
 - 3. Equipment beyond life expectancy





Physical Assessment

ADA Code Compliance / Taft Middle School

- 1. Non-compliant fixtures and stalls in restrooms
- 2. Non-ADA casework and sinks
- 3. Non-compliant stairs / guard rails, no handrails
- 4. No ADA accessible seating
- 5. Food Service:
 - 1. Serving equipment cannot maintain proper temperatures
 - 2. Undersized equipment
 - 3. Equipment beyond life expectancy







Physical Assessment

Cost / Taft Middle School

Site Improvements \$ 676,280

Building Exterior \$ 2,446,692

Interior Deficiencies \$ 1,242,900

Mechanical \$ 1,931,320

Electrical \$ 1,532,760

Food Service \$ 339,200

SUBTOTAL \$ 8,169,152

HARDING MIDDLE SCHOOL


- 115,445 GSF
- 750 NSF AVG
 CLASSROOM








Site Deficiencies


- Parking diagonal & longitudinal slope in excess of 2.0%
- 2. Compliant ramp makes longitudinal walk non-compliant
- 3. Walk in excess of 2.0% cross slope
- 4. A-H: Non-accessible exit / entrance
- 5. No lighting

















Physical Assessment Cost / Harding Middle School Site Improvements 680,414 **Building Exterior** \$ 2,446,692 **Interior Deficiencies** \$ 1,390,770 \$ 1,289,600 Mechanical \$ 1,559,260 **Electrical Food Service** 307,400 **SUBTOTAL** \$ 8,674,136

